

N.C. DEPARTMENT OF HEALTH, ENVIRONMENT AND NATURAL RESOURCES

Groundwater Section

UNDERGROUND STORAGE TANK(S)

SITE NAME:

Pomona School

REGULATED

NONREGULATED

✓

	<u>YES</u>	<u>NO</u>
RELEASE CONFIRMED:	<u> </u>	<u>✓</u>
CLEAN-UP INITIATED:	<u> </u>	<u> </u>
TANK(S) REMOVED:	<u>✓</u>	<u> </u>
RELEASE UNDER CONTROL:	<u> </u>	<u> </u>
CLEAN-UP COMPLETED:	<u>✓</u>	<u> </u>

TECHNICIAN:

Ullberg

DATE:

1 / 25 / 95

COMMENTS:

☒ USGS MAP
☒ BASE MAP
☒ ORIENTATION OF UST
16.1 ~~16.1~~ LENGTH OF UST
8.1' DIAMETER OF UST
6K ~~6K~~ VOLUME OF UST
heat oil MATERIAL STORED
☒ SAMPLE LOCATIONS
13' DEPTH OF SAMPLE
floor SIDE OR FLOOR SAMPLE
3' DEPTH OF TANK BURIAL
trackhoe HOW SAMPLE WAS COLLECTED
40C. SAMPLES PRESERVED AND TRANSPORTED
☒ TOOLS DECONTAMINATED
12/6/94 TIME/DATE SAMPLE COLLECTED
12/7/94 TIME/DATE LAB RECEIVED
BDL LAB RESULTS
3550
5030 ANALYSIS METHOD
☒ C.O.C.
☒ REFERENCE TO SAMPLING POINT ON MAP
No CORRECT # OF SAMPLES needed 3 took 2
12/13/94 WITHIN 14 DAYS HOLDING TIME FOR SAMPLES
Safeway TANK DESTINATION
NA DISPOSITION OF SOIL
12-6-94 REMOVAL DATE
☒ COMPLETE GW/UST-2 FORM

note - Safeway report
indicates 6K tank
Field notes - measurement
was ~16'.
Report referencing 10K
and 21' is incorrect
will send revised
report.